



Anschluss von Widerstandsfühlern


Connection of Resistance sensors



Zweileiter
two-wire



Dreileiter
three-wire



Vierleiter
four-wire